

# QUALITY ALERT!

20 October 2017  
Maximo REF No. n/a



## Core Rot in Hardwood Transmission Poles

### ISSUE IDENTIFIED:

All Hardwood treated (HWT) poles are susceptible to **core rot**, an example of core rot is shown in *Picture 1*. These poles tend to have straight longitudinal grain and a smooth surface. **Radial cracks** can occur and may extend to the centre of the pole allowing **moisture ingress** to the **untreated centre**. Core rot can therefore occur at any point along the pole length, but typically **starts below ground** and works upwards throughout a 3-4m length of the pole.

The type of hardwood species may be identified by the species code on the pole identification disc, see *Picture 2*. Typical HWT poles on the network are “BB” Blackbutt; “RI” Red Ironbark; “NI” Narrow-leaved Red Ironbark and “SG” Spotted Gum. Generally BB poles have been found to have the greatest magnitude of core rot on our HWT poles to date.


**Extra care** is therefore required during **Condition Assessment (CA)**, particularly where radial cracks are identified, as whilst from an **outward appearance** poles can appear to be in **good** condition, **core rot** may have **developed**. For this reason **hammer testing** of all HWT poles should be conducted along the pole length with **special attention** paid to locations **where cracking** is observed. The sound reflections of the hammer blows can be a **good indicator** of the presence of core rot thereby prompting additional investigation. **Good CA practices** on Pi-Pole 70 EDG-KAW A line were successfully applied. The pole diameters were right 300mm and left 308mm at the test bore points. After initial CA measures **identified concerns** these poles were then drilled (*Picture 3*) to confirm presence and magnitude of **core rot**, approximately **100mm** found in the right pole and **120mm** in left.



Picture 1



Picture 2



Picture 3

### CONTRIBUTING FACTORS:

- Chromated Copper Arsenate (CCA) treatment protects outer layer sapwood only, not the core heartwood

### ACTIONS TAKEN TO PREVENT REOCCURENCE:

- Discuss this Alert with appropriate staff
- Ensure CA staff are fully aware of this issue and ensure it forms part of their CA process
- These poles, when changed out, will be cut in cross section to display the level of core rot
- These cross sections will be sent to Omaka and be used for training purposes

### LEARNINGS FROM THIS

- Extra care is required when carrying out CA on HWT poles, in regards to identifying core rot
- An engineering review will be undertaken to provide guidance in regards to CA coding and actions to be taken
- Service Specifications/SMP will be updated as required following the Engineering review



Quality Alert REF No : 2017-007

For more information, please contact:

Name: John A Wilson  
Designation: Service Delivery Manager  
Ph: 06 590 6028 Mob: 021 655 436  
[john.wilson2@transpower.co.nz](mailto:john.wilson2@transpower.co.nz)