


Defective wiring insulation within panel trunking

EVENT

- During scheduled Manapouri Protection maintenance, wiring was moved in the panel trunking causing it to short out. This resulted in a blown fuse on a shared supply for the "GEN-I Trip" Circuit.
- Wiring in the panel had been previously stripped back and left, allowing the copper cores to be exposed (see red circle in photo).
- Further investigation identified that the crimp terminations were also not heat shrunk.



Wires with exposed live copper, and terminations not heat shrunk down.

IMMEDIATE ACTIONS

- Work on the panel was stopped and NGOC informed of the blown fuse.
- Circuit traced and Gen I Trip cct isolated from Transpower protection circuitry as a precaution while the wires were reinsulated and the fuse replaced.
- Reported issues and event to management and incident report created.

Lessons learned

- Never leave wiring in a poor or unsafe state as this will catch someone out in future.
- Terminations must be "made off" to a finished or completed standard as per the manufacturers specification.
- Maintainers need to be vigilant in checking wiring and equipment that they are working on due to possible previous poor workmanship or deterioration that may have created additional hazards.