

Plastic ducting pipe dropped from height into pit bottom.

What happened?

The Principle Contractor (PC) were lowering a stillage containing plastic split ducting into the shaft on the Eltham side.

The stillage was being lowered with the use of a 60t crane. On completion of the lift it was established that one of the sections of ducting had come out of the stillage and had fallen to the pit bottom.

There was a full exclusion zone in place at the pit bottom. No injuries to persons or equipment damage.

The incident was reported and the area was checked and made secure. A Safety stand-down took place on 10th June and an incident investigation is underway.



Incident date: 07/06/2024

Location/Site:

Hurst headhouse LPT2

Responsible ET department:

ID&D

Principal/Contractor:

HMJV

Key contact(s)

Reported by: Barry O'Connor

Line manager: Raja Khan