


A linesperson was observed unclipped whilst working on an OHL tower.

What happened?

Operatives from CLC (tower painting contractors) subcontracted by Morrisons were painting strengthening steelwork approx. 4m above anti-climb guards.

An operative was observed for a short period of time to be unclipped from the tower when work positioning.

The operative was instructed to climb down safely, and work at that site has been stood down pending investigation.



Note: image not of the incident but taken on site visit to the incident location.

Incident date: 06/06/2024

Location/Site:

ZDA Tower 140

Responsible ET department:

Asset Operations

Principal/Contractor:

Morrisons Energy Services

Key contact(s)

Reported by: Martin Bage

Line manager: Phillip Webb