



Isolator Failure during an on-load changeover

What happened?

An On-load changeover was taking place when Isolator 184 failed. Due to load current put through the Isolator the centre phase melting the main contacts. No staff were hurt and TNCC operationally switched the Circuit (CCT) out to stop the flow of load current



Reported date: 06/09/2024

Location/Site:

KINGSNORTH 400KV S/S:
KINGSNORTH POWER STATION SITE,
HOO ST. WERBURG, NEAR
ROCHESTER, KENT ME3 9NQ

Responsible ET department:

Asset Operations

Principal/Contractor:

N/A

Key contact(s)

Reported by: Ethan Whittaker

Line manager: Alastair Clifford

Project Engineer: N/A