


# SAFETY ALERT

## What Happened

This safety alert is issued due to a conduit carrier falling of a vehicle in an unknown location. After finishing for the day an employee noticed the conduit carrier connected to the roof rack of VQYE257 was missing.

The bracket connecting the carrier to the roof rack was a Rhino Rack K & C Conduit Bracket. As can be seen from the photo on the left of another vehicle checked the bracket on the conduit carrier has begun to move and will eventually detach.



## Recommendations/Actions

- All fittings on roof racks are to be checked immediately that they are fitted securely.
- All bolted connections should be checked at regular intervals (every 1000k (621mi) is recommended, depending on road conditions, usage, loads and distances travelled). As these vehicles are used in off road activities these intervals should be reduced.
- Whilst doing the monthly vehicle checks all attachments to the roof racks shall be inspected for security as per the check list.

Issued By  
Tony Beaumont  
H & S Manager  
04/07/2025