



SHE ALERT

LV Flashover



Date of incident:	10/11/2025		Directorate	Services SHEPD	
Region	Customer Operations	Location	Perth	Classification	Potential to be Worse
What happened ?					
<p>Our colleague attended site to carry out a Low Voltage (LV) 1ph service straight joint.</p> <p>On entering the joint bay and beginning the service connection works, our colleague began to strip the outer sheath of the 1ph service cable when an electrical flashover occurred, the event resulted in a burn to their left thumb.</p> <p>First aid was administered at the scene, where a cooling gel pack was used. The injured party(IP) was then taken to hospital where the burn was cleaned and dressed and thereafter was released with no further medical treatment.</p> <p>As we investigate the incident further, please consider the following while carrying out LIVE Jointing works:</p> <p>Operational Safety Manual - Operational Safety Manual – SSEN</p> <p style="text-align: center;">Utilise your safety licence. If it's not safe we don't do it!</p>					



Service Potend & Damaged Service Cable



Burn to AP's thumb