

Date Issued: 05th October 2017

ICAM 49: Stock Truck Hit Conductor – Gore
Riversdale Highway

Event Details:

1400hr Tuesday 01st August 2017

A Transformer Pole with a Low Voltage road crossing was being straightened; this caused the road crossing conductors to sag. A stock truck passed through the worksite and caught one of the Low voltage conductors, the conductor broke. A trainee was attached to the pole that attached the Low Voltage conductor when the stock truck passed through the site.

Why ICAM:

The potential for serious injury to the Trainee Line Mechanic was high. We care about the public and our workmates and none of us want to see this type of event happen again. An ICAM is designed so that the root cause is determined and the correct measures are put in place to prevent the incident from happening to others.



ICAM 22 Outcomes:

1. Leaders to hold discussions with all team members around the importance of thorough site risk assessment and communication onsite with related parties and contractors.

Contact: For further information please contact Michelle Henderson 027 204 4864

