

Safety Bulletin No. 13/2017

POLE MOUNT CUT-OUT FUSE – HENLEY PC400

Issue date	18 December 2017
Issued by	Vincent Cranny, Head of Health, Safety & Environment
Applicable to	Overhead Linesmen and Engineers

ENW have been notified of the following incident in another DNO.

During the loosening of the fuse carrier wing nuts on a Henley PC400 Pole Mounted Fuse Cut-Out, a 'circlip' became dislodged causing the fuse to separate from the carrier resulting in the fuse being retained in the fuse mount.

When unwinding the wing nuts as soon as resistance is encountered no further pressure should be applied as this may cause the 'circlip' shown below to fracture or pop off and result in the fuse holder coming adrift of the fuse.



Safety

