

General

PPE

Vehicles
& Plant

OHL

Tree
Cutting

Cables

Sub-
stations

Metering

SAFETY CRITICAL **INFORMATION** **FLASH BULLETIN**



SCI Number: 17/07

Date of Issue: 22 June 2017

Subject: Cumberland/ SOGAGE MEWP - Catastrophic mechanical failure

Target Audience: All Staff

Detail:

Yesterday afternoon during Tree Cutting work a Cumberland/ SOGAGE A314 MEWP (Photo 1) suffered a catastrophic mechanical failure. This caused the MEWP to detach from the vehicle and fall. The MEWP operator was injured as a result of the fall and taken to Hospital.



Photo 1

Investigations are in progress and we now know that a failure occurred at the turret of the MEWP (Photo 2)



Photo 2

Actions

All Team Managers and Drivers of Cumberland/ SOCAGE A314 MEWPs have been instructed that **the MEWP must not be used.** This restriction must be enforced until further instructions are issued.

There is no restriction on driving the vehicle

This list shows the affected Vehicles and MEWP's

AGZ2914	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ3565	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ3567	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ3571	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ3572	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ9490	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ9493	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ9494	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ9495	Isuzu	D-Max 4x4 MEWP Cumberland
BGZ9496	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ2302	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ2303	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ2305	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ2308	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ2309	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ8750	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ8751	Isuzu	D-Max 4x4 MEWP Cumberland
CGZ9576	Isuzu	D-Max 4x4 MEWP Cumberland
DGZ9915	Isuzu	D-Max 4x4 MEWP Cumberland
DGZ9918	Isuzu	D-Max 4x4 MEWP Cumberland
DGZ9921	Isuzu	D-Max 4x4 MEWP Cumberland
DGZ9924	Isuzu	D-Max 4x4 MEWP Cumberland