



Safety Advice 16-2013 (May) (NZ)

Transformer HV Bushing Fault

Asset owners with high voltage, resin bonded, oil-oil transformer bushings are advised to visually inspect both sides of the bush for concentric cracking that could indicate the bush has delaminated. The following photographs show examples of the type of cracking. The matter is being investigated and an update will be provided as additional information is made available

+++++



