



Safety Advice 45 - 2017 (NZ)

Aichi EWP – Failure of weld in boom support

Powernet have been working with the local Aichi agents to resolve the issue.

Since the alert was issued, Powernet have had the suspect weld re-inspected which confirmed that problem was an overlapped weld. This has since been ground back, and has been re-assessed using a magnetic particle inspection, and passed as OK.

+++++