
## SHE ALERT LV Cable Flashover





Date of incident which is raised in days		30/07/2024		Directorate	SEPD Customer Operations	
Region	1	Thames Valley	Location	Bracknell	Classification	PTBW

What happened?

Our operative was in the process of cutting an LV Consac core using an approved set of insulated ratchet cutters to obtain an isolation point for a low voltage fault to be repaired.

Whilst carrying out this operation a flashover occurred, where the Consac sheath pierced the insulation of ratchet cutters.

Staff are reminded to always follow live jointing working procedures, only one core should be exposed at any one time. Always shroud your neutral conductor.

A full investigation is underway and learnings will be shared.

