

Safety Awareness Notification

Operative struck on the back of head

Operative struck on the back of the head by bowser lid

What happened?

A machine operative was refilling an Auto Dump truck (ADT). As he was placing the hose the lid of the fuel bowser closed. The lid struck the operative on the back of the head, and the back of his shoulders.

The operative was wearing a bump hat; however, he was treated by First aider as a precaution.

No cuts or bruises were observed, and the operative went home.

The injured party (IP) later attended his local A&E hospital, he was treated for mild concussion.



Reported date: 26-03-24

Location/Site: NECTON 400KV S/S: OFF A47, NR NECTON Responsible ET department: Customer Connections

nationalgrid

Principal/Contractor: Burns Mcdonald

Key contact(s)

Reported by:Mark StasiorowskiLine manager:Mark Prescott

Project Engineer: N/A

Accountable person: Mark Stasiorowski

IMS reference: 585921

Issue date: April 2024

-

View the safety bulletins archive on Grid:home Uncontrolled when printed