

Power Quality

John He – Graduate Electrical Engineer (Powerco Ltd)


1

Agenda

1. LV overvoltage
2. Harmonics
3. Light flicker
4. Motor shorting
5. PQ monitoring of the Kapuni 11kV DG site


2

1.1 LV Overvoltage – Waveform



3

1.2 LV Overvoltage - Cause




4

1.3 Overvoltage - Solutions

- 1) Apply Line drop compensation at the voltage regulator
- 2) Perform tap change (tap up) on (or all) concerning dist. transformer
- 3) Check Volt-var, volt-watt setting on solar inverter is active



5

2.1 Harmonics – Waveform



6

2.2 Harmonics – Cause




- Z_h (system impedance) = $Z_1 + Z_2 + Z_3 + Z_n$
- V_d (voltage distortion) = $V_1 + V_2 + V_3 + V_n$
- I_d (current distortion) = $I_1 + I_2 + I_3 + I_n$

$$V_d = I_d Z_h$$



7

3.1 Light Flicker – Waveform




8

3.2 Light Flicker – Cause



9


4.1 – Quick Intro to 2-Phase Faults



- 0 Q r }hur0vhtxhqfh fxuuhqw
- 0 Srvlyh0vhtxhqfh fxuuhqw@ qhjdwyh0vhtxhqfh fxuuhqw
- 0 E skdvh fxuuhqwihhg wkh idxw@ F skdvh Fxuuhqwidxwuhwkuq sdwk


10

4.2 Motor Shorting -Waveform



11

4.3 Motor Shorting - Cause




12

Kapuni Solar Plant PQ Monitoring Project




13

5.1 Present Solar Plant Connection to Network



14


5.2 Proposed Network Change



15

5.3 Project Cost and Timeline

8DJH RR RMU unit cost, with CT and VT	\$41,470.00
A-Eberle PQ-DE monitoring instrument	\$4630.00
RMU Installation cost	\$20,000.00
1kVA single phase TX:	\$1,500.00
DC Supply Power converter	\$500.00
Moxa 3120 communication device	\$2,000.00
Pole modification works	\$18,000.00
Expected Cost	\$88,100.00



16

Questions