



Event Number: 181162

Event Date: 17/08/2025

Event Classification:

WHAT HAPPENED

Workers were requested to work in and around exposed live HV PILC cables.

IMMEDIATE ACTIONS:

Work was suspended and the cables covered.


Safety Reminder

The EEA Guide to Safe Work with Cables clearly states:

"Live paper insulated lead covered (PILC) cables, both HV and LV, and pressurised cables must not be handled under any circumstance"

Staff are also reminded of the requirements from an internal Safety Alert issued in 2010

"If other live cables or equipment are sited close to the cable or equipment that is being worked on, barriers should be used to separate them"



For further information please contact: Maarten Tinsel

Email: maarten.tinsel@omexom.co.nz **Phone:** +6421 917620

Date of release: 1/09/2025

This Safety Advisory/Bulletin is for information purposes only and it is not to be relied upon as expert or professional advice or services. You are responsible for obtaining appropriate professional advice.