

# GOOD SAFETY PRACTICES

## Close the door



### WHAT HAPPENED

Outdoor junction boxes (ODJBs), electrical mechanism and control cabinet doors have been found left open.

This can expose electrical equipment to weather conditions, resulting in faults, premature asset deterioration and network disruption.

### ACTIONS/FINDINGS

**Close and secure all doors and covers before leaving the work area.**

Do not rely on pushing the door shut.

Confirm the latch or catch has been fully engaged and rotated into the locked position to ensure it is weather-tight.

Securing doors helps ensure equipment reliability whilst also excluding the potential for ingress of moisture and dust.



Examples where doors have been left unsecured.

Contact name: Glenn Mathewson, Senior HSE Advisor

Contact Email: [glenn.mathewson@omexom.co.nz](mailto:glenn.mathewson@omexom.co.nz)

Omexom Power Services Southern NZ

Date of the event: 13/08/2026

Event number: 224636

Event classification: Plant/Equip/Material

*This bulletin is for information purposes only and it is not to be relied upon as expert or professional advice or services. You are responsible for obtaining appropriate professional advice.*

C2 - Restricted