



SHE ALERT

Rolled Digger



Date of incident	12 th June 2026		Directorate	Services	
Region	Ops SEPD North	Location	Egham	Classification	PTBW
What happened ?					
During fault excavation works the excavator pictured on the right has rolled over whilst manoeuvring. At the time of incident, the operative was wearing their seat belt correctly and sustained no injuries. Whilst we investigate the incident it is important to remember the following. • Always ensure correct digging practices are being followed. • Always wear a seatbelt whilst using a digger and never jump out of the cab if your digger overturns. • If your digger overturns, ensure your own recovery procedure is followed • Ensure complete spill kit is available at all times.					

