

Incident Alert



Incident Title:


Worker received an electric shock

Date of Incident:

Thursday 19 February 2014

Incident Description and Details:

Worker received a minor shock due to an unearthed 230v socket at Takapu Road Sub-Station. This Socket was installed in 2012 as part of the Site Made Ready works (SMR) adjacent to the Desk Top Access Panel.



Recommendations / Lessons:

Be aware of the possibility additional sites may have unsafe installation. If found please ensure they are isolated immediately and reported.

Test all like installations prior to use.

Continue to use protective equipment such as RCD's when connecting to any supply.

Contact Person(s):

Shane Wigmore HSE Advisor

wigmores@transfieldservices.com / 027 506 1431