

Document No:	NA 75	Issue Date:	15 November 2018
Type:	HSS Alert		
Subject:	Fluke T110, T130, and T150 Two-Pole Voltage Testers ("T-Pole Testers") RECALL		
Applicable Areas:	All departments	Applicable Job Roles:	All
Issued By:	HSS	Author:	Rose Mackinnon
Circulation:			
<input type="checkbox"/> All UK Power Networks Staff <input checked="" type="checkbox"/> Asset Management <input checked="" type="checkbox"/> Capital Programme & Procurement <input checked="" type="checkbox"/> Connections <input checked="" type="checkbox"/> Contractors <input type="checkbox"/> Customer Services <input type="checkbox"/> Finance <input type="checkbox"/> G81 External website <input type="checkbox"/> HR & Communications <input type="checkbox"/> ICPs (Independent Connection Providers) <input type="checkbox"/> IDNOs (Independent Distribution Network Operators) <input type="checkbox"/> Information Systems <input checked="" type="checkbox"/> Legal <input checked="" type="checkbox"/> Meter Operators		<input checked="" type="checkbox"/> Network Operations <input checked="" type="checkbox"/> EPN <input checked="" type="checkbox"/> LPN <input checked="" type="checkbox"/> SPN <input checked="" type="checkbox"/> Connections Services <input checked="" type="checkbox"/> Distribution Capital Delivery <input checked="" type="checkbox"/> Highway Services <input type="checkbox"/> Logistics <input checked="" type="checkbox"/> Network Control <input checked="" type="checkbox"/> Powercare <input type="checkbox"/> Transport Services <input checked="" type="checkbox"/> SHE&TTA <input checked="" type="checkbox"/> In Business safety team <input checked="" type="checkbox"/> Safety Reps <input type="checkbox"/> Strategy and Regulation <input checked="" type="checkbox"/> UK Power Networks Services	

Please consult the author if you have any queries about the information below.

Fluke Corporation has identified a safety issue affecting certain Fluke T110, T130, and T150 Two-Pole Voltage Testers ("T-Pole Testers").



As a precautionary measure, Fluke has decided to voluntarily recall all of these products and provide affected customers with new and improved equivalent replacement products.

It is the responsibility of line management to ensure that all appropriate employees are issued with this Alert and their understanding of the contents is checked. This Alert will be subject to compliance audits after 14 days from the date of issue.

This printed document is valid at 15/11/18, check after this date for validity.

The following T-Pole Testers are being voluntarily recalled ("Recalled Testers"):

Model Name	Manufacturing Dates	Starting Serial No.	Ending Serial No.
FLUKE-T110	up to Jul 2018	2157000 or 21570000	4352999 or 43529999
FLUKE-T110/VDE	up to Jul 2018		
FLUKE-T130	up to Jul 2018		
FLUKE-T130/VDE	up to Jul 2018		
FLUKE-T150	up to Jul 2018		
FLUKE-T150/H15	up to Jul 2018		
FLUKE-T150/VDE	up to Jul 2018		
FLUKE-T150VDE/H15	up to Jul 2018		

The Fluke T90 is NOT impacted by this recall. In addition, all T110, T130, and T150 T-Pole Testers shipped from Fluke after August 28th, 2018 and with serial numbers greater than those specified in the last column above are NOT impacted by this recall.

Please IMMEDIATELY STOP using affected T-Pole Tester and contact Norwich Instruments on 01603 416 900 to arrange a recall replacement.

It is the responsibility of line management to ensure that all appropriate employees are issued with this Alert and their understanding of the contents is checked. This Alert will be subject to compliance audits after 14 days from the date of issue.