

Issue No:	NA 60 Version 2	Issue Date:	03 August 2017
Type:	Safety Alert		
Subject:	Recall of Toyota Hilux MEWP Vehicles		
Applicable Areas:	SPN/EPN	Applicable Job Roles:	Linesmen
Issued By:	Peter Vujanic	Author:	Chris Richardson
Applicable to:			
<input type="checkbox"/> All UK Power Networks Staff <input type="checkbox"/> Asset Management <input checked="" type="checkbox"/> Capital Programme <input type="checkbox"/> Connections <input checked="" type="checkbox"/> Contractors <input type="checkbox"/> HSS&TT <input type="checkbox"/> Meter Operators <input type="checkbox"/> UK Power Networks Services		<input type="checkbox"/> Network Operations <input checked="" type="checkbox"/> EPN <input checked="" type="checkbox"/> SPN <input type="checkbox"/> LPN <input type="checkbox"/> Commercial Services <input checked="" type="checkbox"/> Transport Services <input type="checkbox"/> Logistics <input type="checkbox"/> Network Control <input checked="" type="checkbox"/> Safety Team	

Please consult the author if you have any queries about the information below.

This replaces NA 60 which has been withdrawn.

UK Power Networks has made the decision to recall and suspend the use of all 49 Toyota Hilux vehicles fitted with mobile elevating work platforms (MEWPs). All Toyota Hilux MEWP vehicles are being withdrawn from service by 09:00am Friday 04/08/17.

The driver of any vehicle listed in Table 1 is required to conduct visual checks on the wheel nut indicators to ensure they are tight prior to returning their vehicle to the designated depot as instructed by their Area Manager.

This decision has been made as a result of feedback and concerns raised by drivers and from the ongoing recent investigations into AIRLine reports of loose wheel nuts, which culminated in a number of instances where a wheel became detached from a vehicle. Consequently, UK Power Networks has decided that until all remedial actions are completed on these vehicles, our employees or the public will not be placed at undue risk due to their continued use.

Please note - this recall does NOT apply to Toyota Hilux pick-up trucks that do not have a MEWP fitted or Toyota Hilux company cars.

Remedial actions being taken prior to the Hilux vehicles being returned to service

These are:

- Replacing the wheel nuts and studs and then torquing to 120Nm;
- Fitting of wheel nut indicators;
- Fitting or modification of air suspension where required;
- Weighing of the vehicle to ensure it is below the 3.5 tonne gross vehicle weight;
- An enhanced monitoring programme for these vehicles by our service agents.

A number of options are being actively considered to minimise impacts in the interim period. These will be communicated in due course.

It is the responsibility of line management to ensure that all appropriate employees are issued with this Alert and their understanding of the contents is checked.

This Alert will be subject to Compliance audits after 14 days from the date of issue.

Reminder of Safe Working at Height

Overhead linesmen affected by the suspension of these vehicles are reminded, that when working at height they must continue to apply the working at height hierarchy of control measures and justify which method is adopted on the point of work assessment.

Table 1: Affected Vehicles

Registration	Manufacturer	Model Description	Vehicle Type Description	Region/Area
LN65YNH	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNL	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNK	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNC	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNE	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNF	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LN65YNG	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LR63FSX	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LL15LXG	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LL15LXH	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA BURY
LK15UZU	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA CAMBRIDGE
LP14WYW	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA CAMBRIDGE
LO63DWX	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA CAMBRIDGE
LM63BOH	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA CAMBRIDGE
LR63FNP	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA CAMBRIDGE
LR64NJX	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA COLCHESTER
LM13OVJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA HAROLD HILL
LM14WEH	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA HAROLD HILL
LP14XBN	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA HEMEL
LT65ORJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA KINGS LYNN
LT65ORK	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA KINGS LYNN
LT65ORH	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA NORWICH
LP14WYV	TOYOTA	HILUX SINGLE CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA NORWICH
LN64NLA	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA STEVENAGE
LN64NLE	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS AREA STEVENAGE
LK63WVA	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS BRIGHTON
LM13OUS	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS BRIGHTON
LM13OVH	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS BRIGHTON
LM13OUU	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LM14WEJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LN64NLJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LN64NLP	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LT11KPN	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LT61MDO	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST KENT
LM13OUV	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST SUSSEX
LM13OVF	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST SUSSEX
LT61MDX	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS EAST SUSSEX
LM13OUW	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS MID KENT
LM14WEC	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS MID KENT
LM14WEF	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS MID KENT
LN64NLK	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS MID KENT
LT61MDJ	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS MID KENT
LM14WEO	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST KENT
LL14VNO	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST SUSSEX
LM13OVE	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST SUSSEX
LK63WVB	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST SUSSEX
LM13OVG	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST SUSSEX
LT11KPO	TOYOTA	HILUX EXTRA CAB 2.5 DER/MAN	4X4 TRUCK + PLATFORM	NETWORK OPS WEST SUSSEX

It is the responsibility of line management to ensure that all appropriate employees are issued with this Alert and their understanding of the contents is checked.

This Alert will be subject to Compliance audits after 14 days from the date of issue.