



## *Safety Advice 13-2012 (Nov)(Aust)*

---

The following Safety Advice concerning a fatal EWP boom failure is circulated to EEA members courtesy of EWPANZ.

An EWP operator in Australia was killed when the jib supporting the bucket of the EWP he was operating failed, causing him to fall approximately 20 metres with the bucket. The EWP was an Italmec model Ital Jib 42N. The failure occurred between the jib luffing ram attachment points.

The full alert issued by Worksafe Australia can be viewed on the EWPANZ website - <http://www.ewpa.org.nz/Default.aspx?pageId=1457033>

+++++