

# Rolled ankle whilst stepping off tower footing

#### WHAT HAPPENED?

On Monday 2<sup>nd</sup> March 2015, a tower painter climbed down the C leg of a tower, onto the concrete footing and placed his left foot onto the grass below him. It was approx 500ml depth from the top of concrete pad to ground level. Employee rolled his ankle causing a soft tissue injury (sprain).

Concrete footing where employee stepped off



Unven surface hidden in long grass where employee landed



### **IMMEDIATE ACTION TAKEN**

- Work activity stopped to discuss incident
- Employee was taken to hospital for an assessment

## **ROOT CAUSE**

Failure to identify the hazard (uneven surface)

#### **LEARNINGS**

When reviewing uneven surfaces in the daily tail gate meeting, employees need to physically view and assess the work site surroundings prior to starting work each day



For more information, please contact:

Name: Sarah Kane
Designation: New Plymouth
Ph: 027 269 2355
Skane@fitzroy.co.nz