

Safety Advice 05-2013 (Apr)(NZ)

Transfield Services Incident Alert dated 6 April 2013 concerns a tracked digger roll over while alighting a low loader. The incident is under investigation and any further information will be supplied as a supplementary advice as this becomes available.

The initial incident outline including contact details for further information follows.

Incident Alert





Incident Title: Digger Roll Over

Date of Incident: Saturday, 6 April 2013

Incident Description and Details:

When unloading a digger from a low loader, the digger slid off the ramp and landed on its side. The operator received a cut to his head.

Work was immediately stopped; the injured employee was taken to receive medical attention, where 5 stiches were given.

Actions were then put in place to right the machine and proceed safely.

Recommendations / Lessons:

This incident is currently under investigation.

Contact Person:

Darryl Fernandes, Service Centre Manager, +64 27 451 3015