

Date Issued: 11th July 2017

Incident Title: IWR BOW Shackle Product Recall



Event Details: Crane Association NZ have issued a product safety recall on all “IWR BOW Shackles and Pins with the markings as shown above, the range of recall are rated at working limit WLL 1.0T to WLL 25T. There is a concern that the harness of the Shackle Pin maybe prone to fatigue crack initiation from stress raisers. This could result in fatal injury and or damage to the user or surrounding area.

Immediate Action:

1. All IWR Bow Shackles that have a yellow pin and rated between WLL 1.0T and 25T must be removed from service immediately and given to your Supervisor.
2. Your Supervisor will arrange replacement pins for the affected Shackles and return them to you when this is done.
3. If there is any doubt in regards to the colour of the shackle then quarantine the item and give the shackle to your Supervisor.

Contact for Further Information: Justin Peterson GM HSEQ - 0276031119