



Near Miss in a Confined Space at Hayward's.

No injury

EVENT

On Friday 13th June 2014 at 12:20pm a near miss incident occurred just inside the top gate at Hayward's substation. A contracted hauling crew were identifying a route for a fibre cable pull when one person climbed into a confined space without a gas detector and correct permit. This was immediately noticed and reported.

This is a strong reminder of the risks associated with entering a confined space in a restricted area without first identifying potential hazards

IMMEDIATE ACTIONS

- Work was halted when reported.
- Investigation started with contractor
- Investigations are continuing to stop this happening again.



For more information
please contact:

Name Danny Kooyman
Designation H&S Practitioner
Ph: 06 590 0631
danny.kooyman@transpower.co.nz

