

TRANSPOWER

ElectroNet
DESIGN. BUILD. DELIVER

Event Occurred:
10th August 2021
Maximo Ref: 140890



FIRST ALERT

Water Hose Disconnection – Spraying Water toward T1 33kV at Hangatiki


EVENT

On 10th August 2021 water from a contractors hydrovac truck was being transferred, via a hose, into a trailer mounted water blaster.

During the operation, an observer noticed water starting to spray at the hose coupling of the trailer mounted water blaster. A call was made to turn the water off.

As the operator was moving to turn the water off, the hose came free from the trailer mounted water blaster inlet coupling and sprayed a solid stream of water up toward the red phase on the T1 33kV conductor.

No outage or harm occurred.



IMMEDIATE ACTIONS

- All work ceased
- An investigation has commenced



For more information
please contact:

Name: Tony Beaumont
Designation: Health & Safety Manager
Ph: Mob: 027 297 5445

[email tbeaumont@electronet.co.nz](mailto:tbeaumont@electronet.co.nz)