


SHE ALERT

RTC – Potential to be Worse



Date of incident	25 th April 2024		Directorate	Operations SEPD	
Region	Thames Valley	Location	Witchurch	Classification	PTBW
What happened					
<p>Our colleague was travelling to a fault which was in an off-road location. Access to the location was via a metal trackway which had been installed by a third party.</p> <p>As part of works, our colleague was required to use the trackway multiple times throughout the day. As they were coming back from moving a generator, one of the metal plates dislodged, causing it to lift up and hit their vehicle.</p> <p>The impact from the metal plate caused damage to the vehicle and the airbags were deployed. While we are investigating this incident it is important to remember:</p> <ul style="list-style-type: none">• Always ensure the trackway you are using is suitable.• Ensure that you adhere to the stated speed limit.					

