


SHE ALERT

Cut Chin



Date of incident	31 st July 2024		Directorate	SEPD Operations	
Region	CMI	Location	Grazeley	Classification	MTI
What happened ?					
<p>Our colleagues were removing poles and a PMT due to a wayleave termination. The tension was taken on the steel work with a Hiab to allow our colleague on the top of the pole to remove the bolts.</p> <p>When our colleague removed the bolt, stored energy was released resulting in the steel work rising up and striking them on the chin. First aid was administered, and they went to A&E where surgical glue was applied to close the wound.</p> <p>While we are carrying out an investigation into this incident, please remember:</p> <ul style="list-style-type: none">• To consider the size of the load you have, could you make it smaller?• Your positioning, always keep out of the line of fire. <p>This incident is a good reminder of our ‘Where's the harm in that?’ campaign, so in your teams please discuss;</p> <p>What would you do differently?</p>					

