


# SHE ALERT

## Fallen Object



Date of incident	04/04/2024		Directorate	Operations SEPD	
Region	Works Delivery	Location	Romsey	Classification	HiPo
What happened ?					
<p>Our colleagues were in the process of changing insulators on a 132kV tower. During this operation, the team had taken down the old insulators and were in the process of installing a new set, when a pulley block, that was not in use fell 30 metres and struck an operative on their safety helmet. There were no injuries sustained as all members of the working party were wearing the correct PPE.</p> <p>As a reminder, when carrying out work at height please remember these important points:</p> <ul style="list-style-type: none"> <li>• Ensure Exclusion zones are in place</li> <li>• Ensure you are wearing the correct PPE at all times</li> <li>• Ensure good communication with all members of the team, if this is not possible then stop works</li> <li>• Ensure equipment is inspected and defect free.</li> </ul>					

