


SHE ALERT

Crushed Finger



Date of incident which is raised in days	22 nd March 2024		Directorate	Operations SEPD	
Region	Works Delivery	Location	Church Crookham, Fleet	Classification	MTI
What happened ?					
<p>A contract partner was involved in a cable pulling operation. The winch was started while he was holding the bond wire with his finger through the eye loop at the end. Upon starting the winch, the bond auto-retracted pulling his right hand into the winch. The eye loop at the end of the winch was compressed onto his finger and his hand was trapped. Our contract partner received first aid on site and was taken to hospital where they received two stitches.</p> <p>Whilst we are investigating this incident it is important to remember to:</p> <ul style="list-style-type: none"> •Ensure you complete a risk assessment before completing all works. •Actively look for hazards and then manage the risks (Line of Fire, People/Plant Interface) •Always ask questions if something doesn't feel right - if it's not safe, we don't do it 					

