

**Whilst stepping off a bus an operative nearly stepped into the pathway of a moving wagon.**

#### What happened?

An operative was taking the site bus up to the 33kV compound from the site offices, the bus pulled in adjacent to the compound for him to alight from the bus and in doing so, he nearly stepped into the path of a muck away wagon.

The operative was wearing his high vision PPE and the Muck Away wagon was adhering to the site speed limit.



Location of incident

Incident date: 14/03/2024

Location/Site:  
Sundon 400kv Substation

Responsible ET department:  
Customer Connections

Principal/Contractor:  
GTDS

#### Key contact(s)

Reported by: Paul Turner