


# SHE ALERT

## Contractor RIDDOR



Date of incident	10/09/2024		Directorate	Operations SHEPD	
Region	Operational Support, SHEPD	Location	Keith	Classification	Contractor RIDDOR
What happened ?					
<p>Our contract partner was working on a third party's site, installing palisade fencing around a secondary substation. At the time of the incident, the IP had been taking pictures of the post excavation(s) when they tripped on the spoil and hurt their wrist.</p> <p>Although the IP initially felt pain at the time of the fall, they didn't think they were injured. This was not reported into SSEN-D's 30 Minute Reporting Line.</p> <p>The IP applied a support and continued working as normal until medical attention was sought 3 days from the event. IP was advised that they had fractured their wrist.</p> <p><b>As the incident is investigated, we would remind our employees and contract partners that <u>all SHE Incidents</u> experienced when working on behalf of SSEN-D shall be reported to the 30 Minute Reporting Line without delay.</b></p>					



Site after works:

