


SHE ALERT

Fractured Leg



Date of incident	1 st October 2024		Directorate	Operations SHEPD	
Region	Operational Support	Location	Monifieth	Classification	Reportable Incident
What happened ?					
<p>Our utility arborist colleague was in the process of transferring branches to the chipper after felling a tree in the proximity to our overhead line. Their foot has become entangled in an object in the undergrowth, and in the process of trying to free their foot they have fallen over and immediately felt pain in their lower right leg.</p> <p>After initial first aid on site our colleague was taken to Ninewells hospital where it was confirmed they had fractured their fibula bone in their right leg.</p> <p>Whilst we investigate the incident further, please remember to continue to Plan, Scan and Adapt throughout the job paying particular attention to the site conditions.</p>					

