

Omexom NZ

Event Number: 175625

Event Date: 1/08/2025

Event Classification: LTI



WHAT HAPPENED

Whilst undertaking planned maintenance on a transformer a flashover has occurred in the low voltage cubicle.

IMMEDIATE ACTIONS:

The injured person was transported to hospital for assessment and treatment.

IMMEDIATE SAFETY MESSAGE

All staff are reminded of the requirements for Low Voltage De-Energised work.

An Access Permit must be in place, with either Low Voltage (LV) Bonds applied or a Task Specific Procedure implemented. Prescribed Personal Protective Equipment (PPE) must be worn at all times.

If you cannot meet the requirements of this then all work must stop and the situation escalated.

Investigation in progress



For further information please contact: Maarten Tinsel

Email: maarten.tinsel@omexom.co.nz **Phone:** +64 21 917 620

Date of release: 4/08/2025

This First Alert is for information purposes only and it is not to be relied upon as expert or professional advice or services. You are responsible for obtaining appropriate professional advice.