


# SHE ALERT

## RTC Class 1



Date of incident	11 <sup>th</sup> November 2025		Directorate	Customer Operations	
Region	Operations North	Location	A34, Botley, Oxford	Classification	RTC1

### What happened ?

Our colleague was driving between depots on the A34 near Botley. They were travelling at approx. 50mph in the outside lane of a dual carriageway, overtaking a Heavy Goods Vehicle (HGV).

The HGV changed lanes whilst our vehicle was alongside, clipping the rear left side of our vehicle in the process. This action caused our vehicle to spin 180 degrees, coming to rest off the carriageway, against the barrier (Road Traffic Collision or RTC Class'1). Thankfully, there were no injuries, and our vehicle was recovered from the scene.

As we investigate the RTC further, please consider the following whilst driving:

- Remain focused at all times.
- Never assume other vehicles have seen you.
- Plan, scan and adapt to changing weather and road conditions.

