

safety alert

Personal Injury - Preliminary

Electrix Event Number 15267

Pole 1 Decommissioning Project

What Happened

Whilst observing an excavator loading demolished concrete into a hopper (to enable crushing) the observer's / operators finger was pinched between a piece of concrete and the side wall of the hopper.



Photograph 1

Hopper

Crusher plant

Concrete spoil for crushing

Note: taken pre event

Immediate Actions

First Aid was applied to the injured person's finger and as a precaution was taken for a medical assessment at the local emergency centre.

Work site was made safe and the crusher plant was placed in quarantine pending investigation.

Findings

The Safety Alert is preliminary as the exact details of the event and extent of injury is under investigation.

Date 12/11/2014

For further details please contact Electrix QSE Coordinator Stephen Noble 021 415303

Safety Alerts are advisory only. They contain limited information on an event which has been investigated and reported and the key findings of the investigation are published as a Safety Alert to highlight the key learnings from the event