



Safety Advice 02-2001 (NZ)

CABLE TERMINATION CUBICLE ACCIDENT

An electrical fitter received serious burns whilst working at an industrial complex, when he reached into a live 11kV cable termination cubicle to measure up the fitting of current transformers. The 11kV switchboard was under construction and had been partially livened.