

FOR ISSUE TO SSE Enterprise and Networks

SAFETY FAMILY IN ACTION

Loose MEWP securing Pin – Vehicle Checks prevented incident



The Driver was carrying out his daily checks and noticed that the boom securing pin on the joint between the boom and the fly Boom had worked loose whilst driving the previous day.

What happened?

- While driving between locations a securing pin worked loose.
- The driver was carrying out his daily Checks on his MEWP which highlighted the issue.
- The vehicle in Question was a Mercedes Sprinter long wheelbase MEWP
- A Fitter was called who rectified the fault.

What action is required?

Everyone: Mobile elevated work platforms **MUST** be checked for the same issue company wide and continue to carry out vehicle checks before use.

Supervisor: Ensure that all staff are briefed to check for the same faults before the vehicle is used.

Manager: Promote High standards of Vehicle checks and highlight the importance of completing them.

Communication by	LSG	✓	Notice board	✓	Tool-box talk	✓	Team brief	✓
Communication complete by (✓)	1 week	✓	2 weeks		1-month		2-months	

Issued by: Paul Yeates, Delivery Manager, Enterprise Lighting

Date of issue: 26:04:2016