

FOR ISSUE TO ALL SSE

# SAFETY FAMILY IN ACTION

## WHEEL NUT ON HILUX SHEARED

The importance of Daily Vehicle Checks



### What happened

Whilst carrying out a daily vehicle check the driver of the HILUX noticed that a wheel nut had been sheared of the front passenger side wheel. This was reported to the driver's manager immediately. All other nuts were checked for security then taken to the nearest garage for repair. The cause of this is unknown.

### A positive Outcome

This incident shows the importance of carrying out your daily vehicle checks prior to driving the vehicle, ensuring it is in a safe and road worthy condition.

### Safety Family Positive Indicators

#### Everyone

EP2.2-I will promptly report incidents, near misses and unsafe conditions.

#### Supervisors

SP1.1-I will set standards and coach others as they work to achieve the expected safety behaviour.

#### Managers

MP4.4-I will take personal action to improve SHE performance by showing rigor and passion.

Communication by (✓)	LSG		Notice board	✓	Tool-box talk		Team brief	✓
Communication complete by (✓)	1 week	✓	2 weeks		1-month		2-months	

Issued by: Graeme Boyd Unit Manager Programmes Group North

Date of issue: 02.06.2015