

## Injury sustained during the moving of stillages with a 15T 'Franna' mobile crane to facilitate the delivery of a Super Grid Transformer (SGT)

On 2<sup>nd</sup> February at approximately 00:30hrs, a plant and vehicle marshal was struck by a 15T 'Franna' mobile crane, sustaining serious injury to both lower legs.

The mobile crane was being used to carry a stillage along a hospital access road in preparation for the delivery of SGT2 (arriving at 0400hrs), the injured party was struck by the crane causing serious injuries to both of his lower legs.

An ambulance was called, paramedics carried out treatment and then transported the individual to hospital.

Works have been suspended, and a full investigation is in progress.

### Actions to be taken within the next 7 days:

1. Brief team on exclusion zones for the plant they are working in the proximity of.
2. Sensible Monitoring shall be undertaken on all sites where there is people and plant interface activities, to include a RAMs review.



**Reported date** 03/02/2025

**Location/Site** Bengeworth

**Responsible ET Dept:** ID&D

**Principle Contractor:** Hyosung

**Subcontractor:** Allelys

**Reported by:** Ryusuke Matsuda

**Does it relate to a Fatal Risk Group?** People and Plant