



Safety Alert – SA263

Broken Eye Bolt

This Alert is applicable to:

Fibre	x	Distribution	x	Transmission	x	Wider Business	x
-------	---	--------------	---	--------------	---	----------------	---

Date of issue: 22/04/2015

Incident	Description
<i>Date of Event</i>	16/04/2015
<i>Location</i>	Hailes Road, Whangarei
<i>Time</i>	13:00
<i>Injuries/Damage sustained</i>	<p>No injuries or damage to plant and equipment.</p> <p style="text-align: center;"><u>Broken eye bolt</u></p> 
<i>Event Description</i>	Following a pole replacement, the eye bolt under the tap-off arm broke.
<i>Initial Actions Taken</i>	<p>The incident was reported to NPSAFE and the damaged product delivered to procurement for assessment.</p> <p>A full recall has been undertaken across all regions, replacing the current stock with a replacement stock.</p>
<i>Actions Required / Messages</i>	<p>Drivers of trucks to ensure removal of any existing stock (if not already done) and obtain replacements from Stores.</p> <p>Procurement findings to be shared.</p> <p>Supplier quality investigation process commenced by the procurement team.</p>
<i>SM-EI Reference/ Hazard Register ID</i>	N/A
<i>This alert was released by:</i>	Steve Plewinski, HSQE Advisor Northern - 029 977 8720