

Incident Alert



Incident Title:

Spare wheel on Trailer broken off.

Date of Incident:

Noticed on Friday 23 January, 2015

Incident Description and Details:

Transfield Services operate a number of Raceway tandem trailers. On Friday 23 Jan the staff member noticed the spare wheel had broken off from its position under the trailer chassis. It is unknown when or where this has occurred.

Recommendations / Lessons:

- If anyone has trailers or plant with the spare wheel positioned under the chassis they should inspect the clamping device and modify it as appropriate
- Transfield Services is having the spare wheels fitted on top of the tow bar with a more substantial attachment device than one stud.

Contact Person:

Peter Worthington – Mobile 027 839 8722

worthingtonp@transfieldservices.com



Trailer with spare wheel



Trailer showing broken stud